

# Fusion 2 Release Notes 2.05.02

## Contents

2.05.02.....	3
Release Summary .....	3
New Features .....	3
22858 Implement an Eiva NaviModel Compatible Export of All Baseline Calibration Data .....	4
35044 Provide Ability to Override Baseline Turn Around Times in Calibration Reprocessing.....	4
35045 Provide Tabulated Historic Sound Velocity Data for Sources During Calibration Reprocessing.....	5
35045 Provide Ability to Select a Different Sound Velocity Source Configuration per Calibration Dataset.....	6
Bug Fixes.....	7
2.05.01.....	9
Release Summary .....	9
Bug Fixes.....	9
2.05.00.....	10
Release Summary .....	10
Hardware.....	10
Firmware .....	11
Software .....	11
New Features .....	11
34868 Expanded Tools for Database Management.....	12
34874 New Range Diagnostics Tool .....	14
34877 New Telemetry Diagnostics Tool.....	15
34900 Allow the use of an external depth sensor with a SPRINT-Nav .....	17
34927 More Detailed Time-Sync Information in Sprint Data Tab.....	18
Bug Fixes.....	19

## 2.05.02

### Release Summary

This software release implements a small selection of new features to support customers' operational needs, but primarily focuses on significant improvement to the speed, efficiency, and stability of the software, to improve the user experience and provide more robust communications with attached instruments.

### New Features


Ref	Functional Area	Description
22858	Calibration Reprocessing	Implement an Eiva NaviModel compatible export of all baseline calibration data.
35023	Instrumentation	Show SSB beacon code in USBL instrument data tab.
35025	Security Key	Update DESKey DK2 drivers to v8.21.24.
35029	User Interface	Allow control of DVL aiding status for Sprint-Nav via the Navigation Status Display.
35044	Calibration Reprocessing	Provide ability to edit turn-around-times for baselines.
35045	Calibration Reprocessing	Provide tabulated historic SV data for available sources.
35047	Calibration Reprocessing	Provide ability to select different SV source configuration per calibration dataset.

## 22858 Implement an Eiva NaviModel Compatible Export of All Baseline Calibration Data

When a PDF report of a baseline calibration is generated, either from the Real-Time Calibration tool or the Calibration Reprocessing tool, an XML file is now created and saved in the same directory as the PDF report. This file contains all the necessary information for the baseline calibration to be reprocessed in Eiva's NaviModel software, as a means of comparing Fusion 2's baseline adjustment results with an independent reference.

## 35044 Provide Ability to Override Baseline Turn Around Times in Calibration Reprocessing


It is now possible to override turn-around-times associated with baselines if it is known that an incorrect value has been recorded. To do this, select one or more baselines in the **Data** tab in the **Calibration Reprocessing** tool, and right click on the **TAT (ms)** column. Select **Override Turn-Around-Time (TAT)** in the context menu.




The screenshot displays the Calibration Reprocessing tool interface. The main window shows a 3D plot of baseline data points and a table of calibration data. A context menu is open over the 'TAT (ms)' column, showing options like 'Toggle Include/Exclude of selected ranges', 'Override Turn-Around-Time (TAT)', 'Reset Turn-Around-Time (TAT) Override for selected ranges', 'View Baseline Data', and 'View All Baseline Residuals'.

Date / Time	Collection No.	Source	Destination	Range (m)	TWTT (ms)	Error 95% (m)	Residual (m)	W-Test	Sound Speed (m/s)	Usage	Status	TAT (ms)	XC (%)
2023-10-05 20:04:25	1	L4-2502	L3-2504	114.752	309.505	0.138	2.278	19.940	1535.09	Include	Rejected	160	
2023-10-05 20:04:27	1	L4-2502	L3-2504	114.749	309.502	0.138	2.275	23.138	1535.09	Include	Rejected	160	
2023-10-05 20:04:29	1	L4-2502	L3-2504	114.749	309.502	0.138	2.275	22.530	1535.09	Include	Rejected	160	
2023-10-05 20:04:34	1	L5-2505	L4-2502	132.080	292.129	0.098	0.083	1.697	1534.66	Include	Accepted	12	
2023-10-05 20:04:36	1	L5-2505	L4-2502	132.076	292.124	0.098	0.079	1.619	1534.66	Include	Accepted	12	
2023-10-05 20:04:38	1	L5-2505	L4-2502	132.073	292.120	0.098	0.076	1.556	1534.66	Include	Accepted	12	
2023-10-05 20:04:34	1	L5-2505	L1-2501	100.488	330.954	0.092	1.992	26.469	1534.71	Include	Rejected	20	
2023-10-05 20:04:36	1	L5-2505	L1-2501	100.489	330.955	0.092	1.993	25.172	1534.71	Include	Rejected	20	
2023-10-05 20:04:38	1	L5-2505	L1-2501	100.485	330.950	0.092	1.989	30.369	1534.71	Include	Rejected	20	
2023-10-05 20:04:34	1	L5-2505	L3-2504	83.017	268.142	0.098	-0.060	1.236	1535.33	Include	Accepted	160	
2023-10-05 20:04:36	1	L5-2505	L3-2504	83.024	268.151	0.098	-0.053	1.094	1535.33	Include	Accepted	160	
2023-10-05 20:04:38	1	L5-2505	L3-2504	83.022	268.148	0.098	-0.056	1.141	1535.33	Include	Accepted	160	

A dialog is shown, where a new value can be set for the selected baseline ranges.




Any changes made via this method can be reset by reselecting the baseline ranges, right clicking on the **TAT (ms)** column, and selecting **Reset Turn-Around-Time (TAT) Override for selected ranges**.



### 35045 Provide Tabulated Historic Sound Velocity Data for Sources During Calibration Reprocessing

While reprocessing calibration data, associated sound velocity can be viewed in a table when available. This information can be viewed from within the Calibration Reprocessing tool by clicking the buttons in the **View Data** column of the tables within the **Sound Velocity** tab.



The screenshot shows the Calibration Reprocessing tool interface. The **Sound Velocity** tab is selected. A table lists sources with columns for Reference, Source, Measured, and SV (m/s). A **View Data** button is highlighted for each source. A dialog box titled **View Sound Velocity Data** is open, showing a table of Date / Time and Sound Velocity (m/s) data for Source Measured: 2501.

Date / Time	Sound Velocity (m/s)
2023-10-05 20:03:11	1490.00
2023-10-05 20:03:20	1490.00
2023-10-05 20:03:52	1490.00
2023-10-05 20:03:56	1490.00
2023-10-05 20:03:58	1490.00
2023-10-05 20:04:00	1490.00
2023-10-05 20:04:03	1490.00
2023-10-05 20:04:05	1490.00
2023-10-05 20:04:07	1490.00
2023-10-05 20:04:30	1490.00
2023-10-05 20:04:42	1490.00
2023-10-05 20:04:44	1490.00
2023-10-05 20:04:46	1490.00
2023-10-05 20:04:48	1490.00
2023-10-05 20:04:59	1490.00
2023-10-05 20:05:11	1490.00

The main table in the tool shows the following data:

Location	Beacon	Easting	Northing	Depth	Semi-Major 95% (m)	Semi-Minor 95% (m)	Theta (°)	Depth Error 95% (m)	State
L1	2501	416747.797	5579656.598	27.000	7.10	5.00	295.85	1.77	Uncalibrated - Fixed Depth
L3	2504	416816.254	5579777.402	22.999	7.30	5.00	301.28	1.80	Uncalibrated - Fixed Depth
L4	2502	416712.562	5579735.120	28.001	7.13	5.00	14.52	1.83	Uncalibrated - Fixed Depth
L5	2505	416836.386	5579698.880	25.000	6.75	5.00	16.41	1.73	Uncalibrated - Fixed Depth

## 35045 Provide Ability to Select a Different Sound Velocity Source Configuration per Calibration Dataset

While reprocessing calibration datasets consisting of multiple individual collections, it is now possible to configure each collection's sound velocity sources separately. This may be useful when multiple sound velocity profiles are available and are associated with specific calibration datasets. When multiple collections are imported to the Calibration Reprocessing tool, the collection number for each baseline is visible in the **Data** table, and each collection's SV configuration can be edited by selecting its number in the drop-down menu before making changes to the configured sources.

The screenshot displays the Calibration Reprocessing tool interface. The top-left panel shows the 'Calibration Type' set to 'Baseline' and 'Sound Velocity' selected. Below this, the 'Data Collection Number' is set to 1. The 'Project' and 'Profile' are both set to 'Demo1\_Reduced'. A table below shows the 'Reference' and 'Source' for each collection, with 'SV (m/s)' values. The bottom-left panel shows the 'Data' table with columns for 'Date / Time', 'Collection No.', 'Source', 'Destination', 'Range (m)', 'TWTT (ms)', 'Error 95% (m)', 'Residual (m)', 'W-Test', 'Sound Speed (m/s)', 'Usage', 'Status', and 'TAT'. The 'Collection No.' column is highlighted with a red box. The right panel shows a 3D visualization of the calibration setup with points labeled L1-2501, L3-2504, L4-2502, and L5-2505. The bottom-right panel shows the 'Location Status' table with columns for 'Location', 'Last min', and 'Total'. The 'Location' column is highlighted with a red box.

Reference	Source	SV (m/s)
L1-2501	Project - Profile: Demo1_Reduced	1534.51
L3-2504	Project - Profile: Demo1_Reduced	1535.76
L4-2502	Project - Profile: Demo1_Reduced	1534.42
L5-2505	Project - Profile: Demo1_Reduced	1534.91

Date / Time	Collection No.	Source	Destination	Range (m)	TWTT (ms)	Error 95% (m)	Residual (m)	W-Test	Sound Speed (m/s)	Usage	Status	TAT
2023-10-05 20:04:50	1	L3-2504	L5-2505	83.025	308.153				1535.33	Include	Not Used	
2023-10-05 20:04:52	1	L3-2504	L5-2505	83.024	308.151				1535.33	Include	Not Used	
2023-10-05 20:04:54	1	L3-2504	L1-2501	142.211	385.275				1535.13	Include	Not Used	
2023-10-05 20:04:52	1	L3-2504	L1-2501	142.207	385.270				1535.13	Include	Not Used	
2023-10-05 20:04:54	1	L3-2504	L1-2501	142.203	385.265				1535.13	Include	Not Used	
2023-10-05 20:19:00	2	L4-2502	L5-2505	129.388	372.275				1502.11	Include	Not Used	
2023-10-05 20:19:14	2	L4-2502	L5-2505	129.390	372.278				1502.11	Include	Not Used	
2023-10-05 20:19:16	2	L4-2502	L5-2505	129.389	372.276				1502.11	Include	Not Used	
2023-10-05 20:19:18	2	L4-2502	L5-2505	129.387	372.274				1502.11	Include	Not Used	
2023-10-05 20:19:20	2	L4-2502	L5-2505	129.390	372.278				1502.11	Include	Not Used	
2023-10-05 20:19:22	2	L4-2502	L5-2505	129.391	372.279				1502.11	Include	Not Used	

Location	Last min	Total
L1-2501		
L3-2504		
L4-2502		

## Bug Fixes

For more details on any of the fixes below please contact Sonardyne customer support.

Functional Area	Ref	Description
Average Fix Tool	35012	Fix incorrect scaling of position error metrics
Alarms	35021	Alarm not raised when beacon telemetry fails
Box-in Calibration	35024	Box-in calibration of location using external Range Input (SSB) fails to start if location already has a beacon assigned to it.
Acoustics	35027	Remove unnecessary MR commands being sent to beacons with low battery which restricted their further use
Calibrations	35031	Sound velocity profile missing from calibration snapshot files
Data Export	35032	Raw Comms data export failing if instruments connected via comms hub
Acoustic Instrumentation	35034	ROVNav information being overwritten by beacon information while performing beacon telemetry.
Telemetry Diagnostics	35036	Some acoustic commands becoming stuck in telemetry diagnostics display indefinitely
Box-in Calibration Reprocessing	35038	Incorrect method of calculating average sound speed for ranges used for sound speed profiles in reprocessing of box-in calibrations.
Box-in Calibration Reprocessing	35039	Software crash which could occur while reprocessing box-in calibration data if live GNSS being supplied to the system
Baseline Calibration Reprocessing	35041	Calibration report generation failing if data is manually rejected
Calibration Reprocessing	35043	Incorrect behaviour of scroll bars in calibration reprocessing tool
Calibration Snapshots	35048	Some settings not being saved when snapshot of current calibration state taken
Baseline Histogram Plots	35050	Incorrect plot scaling makes interpretation difficult
Calibration Snapshots	35052	Progress bar during snapshot generation not showing any progress
Instrumentation	35054	ROVNav transceiver missing from system setup on software restart
Acoustic Instrumentation	35062	High CPU usage in some circumstances if beacon ranging fails
Instrumentation: Sprint	35071	Switching communications from serial to ethernet can cause loss of input configuration
Instrumentation: Sprint	35075	Instability of communications with Sprint after extended period of operation.
User Interface	35076	Depth segment of Navigation Status display incorrectly greyed out in some circumstances
User Interface	35082	User interface unresponsive after extended period of operation if manual command tool left open.
User Interface	35084	Instrument status lights in system setup page showing incorrect connection status for DVL
Communications	35087	Communications to DVL connected via LCH lost if LCH power cycled
Instrumentation: Sprint	35090	Some commands and control of Sprint causing user interface to freeze.
Instrumentation: Syrinx	35091	Outputs from Syrinx auxiliary port incorrectly cleared by Fusion 2 during configuration



Functional Area	Ref	Description
Instrumentation: iWand	35095	Unable to connect to iWand via serial/USB
Instrumentation	35102	Able to add multiple DVL instruments to a vehicle when only one is supported
Security Key	35107	Security key read failure preventing software loading
User Interface	35112	User can move plot series which should be fixed to the axes in aiding diagnostics chart
User Interface	35115	Instrument status lights in system setup page showing incorrect connection status for some instruments after LCH power cycle
Instrumentation	35118	Synchronous communication time stamping strategy causing comms buffering on systems under heavy load
Security Key	35119	Security key read failure causing system instability on long running system
Telemetry Diagnostics	35122	Some pending actions not shown in acoustic telemetry diagnostics window
Baseline Calibration Reprocessing	35123	Calibration reprocessing tool showing incorrect SD figure on chart overlay in some circumstances when multiple datasets loaded.
Box-in Calibration	35131	Box-in calibration failing to compute position for multiple beacon calibrations under some circumstances.
User Interface	35151	Not possible to scroll list of vehicles/transceivers in SV configuration page.

**Note: Versions of Fusion 2 after 2.04.00 will not install/run on Windows 7. For more information on Windows 7 please contact Sonardyne customer support, using the details at the end of these release notes.**



## 2.05.01

### Release Summary

This software release provides fixes to issues found in version 2.05.00 of the software.

### Bug Fixes

For more details on any of the fixes below please contact Sonardyne customer support.

Functional Area	Ref	Description
Beacon import	35016	CSV import fails if it includes beacons which have never been interrogated.
Instrumentation / Beacons	35017	Tracking fails to start when loading legacy jobs where many beacons have unknown CIS state.
Instrumentation / Transceivers	35018	Newly added transceivers can assume identity of other transceivers in system if communication with them is not immediately successful.
Instrumentation / Ranging	35022	Ranging can become slow when receiving more than 15 ranges in one cycle (e.g., during some Fast-LBL structure tracking scenarios).

---

**Note: Versions of Fusion 2 after 2.04.00 will not install/run on Windows 7. For more information on Windows 7 please contact Sonardyne customer support, using the details at the end of these release notes.**

---

## 2.05.00

### Release Summary

This scheduled software release provides new software functionality, improved performance and reliability, addresses issues found in earlier versions of the software and implements usability improvements in line with customer feedback.

Significant new additions and changes include:

- Additional acoustic diagnostics tools
- Expanded database management tools
- Support for external depth sensors with SPRINT-Nav INS instruments
- Additional depth data input formats

### Hardware

The following PC specifications are required as a minimum:

Component	Specification
Processor	Core i7 2.4GHz
Memory (RAM)	8GB
Graphics Card	32-bit colour, minimum 1280 x 1024, Direct-X V10 or later
Operating System	Windows 10 x64

## Firmware

The following instrument firmware versions are the minimum versions which should be installed in each component for use with this software release. Please note that more recent firmware versions may be available and installed on new equipment, there is no requirement to downgrade these instruments for use with Fusion 2

Instrument	Firmware Version
Navigation Sensor Hub (NSH)	2.0.3.107
SPRINT Firmware	3.07.00.2139
Syrinx Firmware	3.02.40.00 (Rel2_revJ)
ROVNav 6+ LBL Transceiver	3.12.08.09
Compatt 6+ LBL Transponder (CPU)	3.13.01.03
Compatt 6+ LBL Transponder (DAS)	2.06N
MiniROVNav 6+	3.12.02.05
MicroCompatt 6+	3.12.02.05
Lodestar Gyro Compatt 6+ (CPU)	3.12.07.13
Lodestar Gyro Compatt 6+ (Lodestar)	3.02.01

## Software

The following associated software versions have been tested with this release. As a minimum, these versions must be installed when used with this release of Fusion 2:

Package	Software Version
Janus	1.06.01.14

## New Features


Ref	Functional Area	Description
34845	Instrumentation	Adds a warning to the use if ZDA time-sync input is detected to be incompatible with current settings
34857	User Interface	Adds acoustic diagnostics information to ranges in measurements window
34860	Instrumentation / UI	Add alarm to inform when unable open a com port.
34863	Instrumentation	Enable system to connect to a SPRINT which has been reset to factory defaults
34868	Database / Data Logging	Adds expanded tools for database management
34871	Calibration / UI	Provides a reminder to export data after completion of a calibration.
34874	User Interface / Acoustics	New range diagnostics tool
34877	User Interface / Acoustics	New telemetry diagnostics tool
34897	Instrumentation	Adds decoder for WINSON telegrams providing depth information.
34898	Instrumentation	Enables logging of new INS diagnostic messages for use in post-processing
34899	Instrumentation	Updated default values for some INS parameters in SPRINT configuration files.
34900	Instrumentation	Allow the use of an external depth sensor with a SPRINT-Nav
34927	Instrumentation	More detailed time-sync information in SPRINT data tab
34992	Application Start-up	Prevents Fusion2 from being opened if SPRINT software is running to prevent SPRINT instrument configuration conflicts.

## 34868 Expanded Tools for Database Management

More advanced tools for the management of the MongoDB database to which all Fusion2 data is logged are now provided. The new capabilities allow the user to:

- See in more detail the size and extents of the database
- Archive an entire database for backup or replication purposes.
- Restore an archived database
- Delete all, or selected portions of, the data within the database.

Basic database information can be viewed by opening the **Tools > Options** window. Further information and management tools can be found by clicking on the **Data Management** button as show below.




The screenshot shows the 'Options' window with several sections. The 'Database Management' section at the bottom is highlighted with a red border. It contains a table with database information and a 'Data Management' button.

Data time range		Database Size
Oldest:	2023-01-23 14:57:16	Newest: 2023-01-23 15:08:35 1.04 MB

Below the table is a button labeled 'Data Management'.

Statistics, archival and deletion options are presented as shown below.


Database Management

Data Statistics

Oldest: 2023-01-23 14:57:16	Data Size (Uncompressed): 1.88 GB	Total Disk Space Used: 453.62 GB
Newest: 2023-01-24 11:22:07	Storage Size (Compressed): 90.54 MB	Total Disk Space: 953.26 GB

Archive Data

Folder
C:\Users\Public\Documents\Sonardyne\Fusion2\Archives\

Name
Archive\_20230124T112228.gz

Archive

Restore

Delete

☒ All Data

Time Series Data:

☒ Data prior to date

☐ Last 'N' Hours

Calibration Data:

☒ Calibration file(s)

Select From time using Bookmark

2023

-

01

-

23

14

:

57

:

16

2023

-

01

-

24

11

:

22

:

07

Delete

Status

History

Status messages will appear here when running a Archive / Restore / Delete ...

Info

Select a Database Management task

Progress


0%

Close

13

## 34874 New Range Diagnostics Tool

A new range diagnostics tool is available and can be opened via the **View> Diagnostics > (Vehicle) > Ranges** menu item.



The tool displays information about each acoustic range which is expected to be received by the transceiver on the selected vehicle, and their use in the selected positioning solution. The solution for which information is displayed can be changed using the drop-down menu at the top of the tool window.

Range Diagnostics - ROV1

Show Ranges for Solution: Solution 1 - LBL

Age	Target	Range	Sound Velocity	Used?	Residual	Signal Quality			
4s	L1-2401	222.308 m	1536.15 m/s	✗	-1.736 m	XC	■■■■■	SL	■
						SNR	■■■■■	IL	■■■■■
4s	L2-2402	107.693 m	1534.81 m/s	✓	0.352 m	XC	■■■■■	SL	■■■■■
						SNR	■■■■■	IL	■■■■■
4s	L3-2403	117.102 m	1532.77 m/s	✓	0.071 m	XC	■■■■■	SL	■■■■■
						SNR	■■■■■	IL	■■■■■
4s	L4-2404	95.102 m	1534.59 m/s	✓	0.426 m	XC	■■■■■	SL	■■■■■
						SNR	■■■■■	IL	■■■■■
4s	L5-2405	126.697 m	1535.71 m/s	—	---	XC	■■■■■	SL	■■■■■
						SNR	■■■■■	IL	■■■■■
118s	L6-2406	167.967 m	---	—	---	XC	■■■■■	SL	■■■■■
						SNR	■■■■■	IL	■■■■■

Range received but rejected by positioning solution


Ranges received and used in solution

Range received but not configured for use

Range not received

## 34877 New Telemetry Diagnostics Tool

A new telemetry diagnostics tool is available and can be opened via the **View> Diagnostics > Telemetry** menu item.



Alternatively, the tool can be opened by clicking on the popup telemetry indicator which appears when telemetry tasks are being carried out.



The tool provides a dynamic overview of all acoustic telemetry tasks as they are queued and actioned, together with their status, the results of the tasks and associated acoustic signal quality information.

Actioned	Target	Task	Status	Signal Quality
15:39:07	L1-2401	<b>Retrieve All Settings</b> Received Fixed Settings - UID:4661, FL:825A, FW:3.12.00.01, OMNI, Sensors:[T, SV, PR] Received Battery Status - 75% Received Acoustic Settings - TAT200, BLK100, RXW4800, TXW100, NPL187, TPL187, LG26, CIS00, AT8, Enabled, EC1 Received Unit Settings - SN22224-011, DR3000, STD, AL6082, 1, TYPE: 8300 <b>Retrieving Sensor Measurement</b>	<b>In Progress</b> Step Complete Step Complete Step Complete Step Complete In Progress	XC SNR SL IL XC SNR SL IL XC SNR SL IL XC SNR SL IL XC SNR SL IL
15:38:57	L2-2402	Retrieve All Settings	Pending	
15:38:57	L3-2403	Retrieve All Settings	Pending	

If an acoustic telemetry task fails, the user can choose to skip, retry, or cancel the task.

Actioned	Target	Task	Status	Signal Quality
15:52:54	L1-2401	<b>Read Sensors</b> Retrieving Sensor Measurement - Reading sound velocity, Max Wait: 4s	<b>Failed</b> Timed Out	XC SNR SL IL XC SNR SL IL
15:53:08	Transceiver1	Read Sensors	Complete	



A history of the acoustic telemetry tasks displayed in this tool is automatically recorded to file for further analysis if required. These files can be found in

**C:\Users\Public\Documents\Sonardyne\Fusion2\LogFiles\TelemetryDiagnosticsLog.**


### 34900 Allow the use of an external depth sensor with a SPRINT-Nav

It is now possible to connect an external depth sensor to a Fusion 2 system which is using a SPRINT-Nav and use it for INS depth aiding. This provides an alternative to the built in SPRINT-Nav pressure sensor.

The SPRINT-Nav and external depth sensor should be added to the vehicle via the system setup page in the usual way:




The desired depth sensor should be selected for use in the appropriate solution in the Navigation Solutions configuration window:



## 34927 More Detailed Time-Sync Information in Sprint Data Tab

Information about the estimated SPRINT time synchronisation quality and the time since last update is now shown in the SPRINT data tab:



The screenshot shows the 'System Setup' window with the 'Data' tab selected. The 'SPRINT' section is expanded, showing a list of data entries. The entry 'Sprint Time Sync Observation: Quality: 500 ms Time Since Update: 258 ms' is highlighted with a red box.

Time	Data
2023-01-24 12:48:07	Roll : 0.03° Pitch : -0.04° Heading : 180.0° HeadingError : --- Source : AHRS
2023-01-24 12:48:07	Latitude : 51.3306406° N Longitude : 0.8356915° W Depth : 0.000 m
2023-01-24 12:48:07	North Velocity : 0.0 m/s East Velocity : 0.0 m/s Down Velocity : 0.0 m/s
2023-01-24 12:48:07	Roll : 0.03° Pitch : -0.04° Heading : 180.0° HeadingError : 0.6° Source : INS
2023-01-24 12:48:07	Altitude : 0.000 m
2023-01-24 12:48:07	Sprint LNAV Observation
2023-01-24 12:48:07	Instrument Time : 3023.030715/25404539807019472 Common Time : 2023-01-24 12:48:07
2023-01-24 12:48:07	Sprint Time Sync Observation: Quality: 500 ms Time Since Update: 258 ms
2023-01-24 12:48:06	SPRINT Self-Test Status : Good Details : Power on port T1 is turned off, Power on port T2 is turned off, Power on port T3 is turned off
2023-01-24 12:48:04	USBL Aiding Status : Good

Buttons at the bottom: Report, Apply, Undo

## Bug Fixes

For more details on any of the fixes below please contact Sonardyne customer support.

Functional Area	Ref	Description
Tracking	34788	Fixes issue which prevented SV profile being read correctly for some system configurations.
User Interface	34855	Fixes issue which prevented a manual sound speed being entered for a vehicle.
User Interface	34865	Several detail fields not being populated for SPRINT and Syrinx instruments, despite successful instrument connection.
Security Key	34848	Fixes issue which prevented features from multiple security keys being used concurrently.
Instrumentation	34859	Prevents multiple instruments being added to a communication port when doing so would result in a conflict.
Instrumentation	34862	Fixes issue which prevented ZDA time-sync being sent to SPRINT instrument
Instrumentation	34864	Improves stability of SPRINT reconnection procedure after instrument is rebooted
Instrumentation	34872	Fixes issue with automatic configuration of power pass-through on SPRINT ports for DVL instruments and Transceivers
User Interface	34884	Improves reliability of power pass-through indicators for Sprint ports.
Instrumentation	34866	Prevent sending of further commands to SPRINT instrument when a reset or shutdown command has been issued.
Instrumentation	34887	Remove obsolete and unnecessary commands from SPRINT default configuration files.
User Interface	34888	Fixes bug which prevented INS heading quality from being plotted on chart
Instrumentation	34901	Prevents sending of unnecessary multi-user commands by systems which don't require multi-user features.
User Interface	34903	Fixes issue which prevented alarm being raised when no heading available in LBL positioning solution.
Beacon Import	34904	Fixes issue which prevented CSV import of beacons when elements of beacon configuration missing.
Instrumentation	34905	Fixes issue which prevented configuration of some Compatt parameters while tracking enabled.
Instrumentation / Tracking	34906	Fixes issue which prevented correct use of SV profile during box-in calibration
Instrumentation	34911	Fixes issue which prevented use of PSONDEP telegram for depth aiding via SPRINT port
User Interface	34915	Improved wording for missing DVL calibration alarms.
User Interface	34920	Fixes issue with visual scaling of data in the text-display
User Interface	34931	Fixes issue preventing correct charting of AHRS data from SPRINT instrument
Outputs	34939	Fixes issue preventing output of DigiQuartz depth data via SPRINT serial port.
User Interface	34943	Fixes display of available job files when opening an existing job file.
User Interface	34946	Fixes issue which caused the DVL status in the Navigation Status display to show good (green) when no data was being received.

Functional Area	Ref	Description
Calibration reprocessing	34951	Fixes incompatibility with old versions of CAS2 files produced by Ranger 2 software, which prevented them from being imported for box-in reprocessing in Fusion 2.
User Interface	34954	Changes time display in average fix tool from 12 to 24 hr format.
Instrumentation	34955	Fixes issue which caused a failed Compatt configuration command to be repeated indefinitely if ranging was enabled and active.
Tracker	34956	Fixes issue which could prevent correct remote point to be output for an LBL solution
Instrumentation / User Interface	34957	Prevents user from changing beacon addresses and/or wakeup tones when ranging is enabled and active.
Instrumentation	34961	Prevents crash which could occur during retrieval of GyroCompatt status.
Instrumentation	34963	Fixes issue which prevented beacon configuration to be changed while tracking on a multi-user channel.
Instrumentation	34965	Fixes issue which could prevent successful INS aiding of SPRINT connected via serial-ethernet device.
Instrumentation	34968	Corrects rendering of beacon sensor data in measurement display when the beacon reports a sensor error.
Instrumentation	34969	Fixes issue which prevented reopening of NSH serial ports when the device was rebooted, or the connection was lost and regained.
Baseline Calibration Collection	34977	Fixes issue which prevents baseline calibration from starting.
Alarms	34988	Fixes issue in which some alarm fields were left unpopulated
Tracking	34994	Prevents output of LBL position derived from fewer than 3 ranges.
User Interface	34995	Corrects information shown in comms viewer when in Observation mode when an output telegram can't be sent.
Instrumentation	34996	Prevents a resetting transceiver from overwriting the currently configured SV collection settings.
Outputs	34999	Ensures that the 'not limited' option is presented as the default when configuring an LBL derived output telegram.
User Interface	35000	Fixes issue which could cause some ranging segments in the navigation status display to show data from previous ranging cycle.
Outputs	35004	Fixes incorrect timestamp format in GGA output telegram.

# Contact Information

For further support please contact:

24/7 Emergency Helpline

T. +44 (0) 1252 877600

Email Support

[support@sonardyne.com](mailto:support@sonardyne.com)

Website

[www.sonardyne.com](http://www.sonardyne.com)