

New Software/Firmware Release Notification

Bulletin No.	SF18-003	Issue Date:	17-07-2018
Issue/Revision:	A	No. of Pages:	1
Prepared By:	James Barnett	Signature:	
Approved By:	Malik Chibah	Signature:	

<input type="checkbox"/> Mandatory <input checked="" type="checkbox"/> Strongly Recommended <input type="checkbox"/> Optional

Subject: Lodestar V3.02 Firmware Release

As part of Sonardyne’s continuous programme of product development, we are pleased to announce the release of Lodestar firmware V 3.02.00.1012.

Main features of this release:

- Support Syrinx Beam Level Aiding*
- Added support for new OBSTDVL message – Integration Option
- Improvement of UDP inputs
- Improvements to Lodestar Trigger monitoring (BIST)
- Improvement on Ethernet for better TCP connections

See Lodestar release notes for full list of changes.

*Beam Level quoted performance in datasheet is for SPRINT-Nav and Sonardyne calibrated SPRINT with co-located Syrinx.

The following instrument firmware versions have been tested with this software version. As a minimum, these firmware versions must be installed in each component when used with this version of software.

Instrument	Firmware	Software	Version
Syrinx	2.2.4.0	SPRINT	1.5.1.440
ROVNAV6 (6G) Type 8311	3.05.06.12	Janus	1.2.1.18
		Fusion LBL	1.12.04 / 1.12.05

If you are not the correct recipient for this information or you would like us to send this information to another person please respond to this email.

You will not automatically receive a copy of this software/firmware.

Should you require any further clarification please contact customer support on support@sonardyne.com or +44 1252 872288.

