



New Software/Firmware Release Notification

Bulletin No.	SF15-014	Issue Date:	10th September 2015
Issue/Revision:	1	No. of Pages:	1
Prepared By:	F.Gilroy	Signature:	
Approved By:	P.Randall	Signature:	

- | |
|---|
| <input type="checkbox"/> Mandatory
<input checked="" type="checkbox"/> Strongly Recommended
<input type="checkbox"/> Optional |
|---|

Subject: WSM6+ Firmware v3.05.00.04 Release

As part of Sonardyne's continuous programme of product development, a new version of firmware has been approved for release. This firmware is applicable for the following products:

- WSM6+ 1K MF Omni (8370-000-1111)
- WSM6+ 1K MF Omni XRVO (8370-000-1211)
- WSM6+ 4K MF Omni (8370-000-4112)
- WSM6+ 4K MF Omni XRVO (8370-000-4212)

This release of firmware fixes a potential vulnerability whereby a break in connection between the motherboard to the pressure sensor on the connector endcap would prevent the firmware from initialising correctly.

Full support for dual external release voltage outputs has been added for the following WSM6+ units:

- WSM6+ 1K MF Omni XRVO (8370-000-1211)
- WSM6+ 4K MF Omni XRVO (8370-000-4212)

Refer to the WSM6+ manual (UM-8370) for firmware upgrade instructions.

If you are not the correct recipient for this information or you would like us to send this information to another person please respond to this email.

You will not automatically receive a copy of this software/firmware.

Should you require any further clarification please contact customer support on support@sonardyne.com or +44 1252 872288.