

Tsunami detection system

Release notes 2.01F

Contents

2.01F	3
Release summary	3
Associated firmware versions	3
Associated software versions	3
Bug fixes	3
Additional information	4
Contact information	4

2.01F

Release summary

This firmware release provides fixes for two identified bugs:

- Errors on D\$2 messages
- Stepwise changes in data

Associated firmware versions

The following instrument firmware versions have been tested with this firmware version.

Instrument	Firmware version
Dunker Test Box	3.05.14.06

Associated software versions

The following associated software versions have been tested with this firmware version.

Package	Software version
6G Terminal	2.04.00.377
Windows	11 (26100.8655)

Bug fixes

Reference	Description
SG-146	D\$2 message values corrected
SG-529	Stepwise changes in data (data resolution issue) corrected

Additional information

Tsunami Detection System firmware builds prior to 2.01F are not documented here. The formal release prior to this was 2.01D; 2.01E was offered to a small number of customers as a beta version but never formally released.

Contact information

For further support please contact:

24/7 emergency helpline

T. +44 (0) 1252 877600

Email support

support@sonardyne.com

Website

www.sonardyne.com