

# New Software/Firmware Release Notification

<b>Bulletin No.</b>	<b>SF18-002</b>	<b>Issue Date:</b>	<b>17-07-2018</b>
<b>Issue/Revision:</b>	<b>A</b>	<b>No. of Pages:</b>	<b>1</b>
<b>Prepared By:</b>	<b>James Barnett</b>	<b>Signature:</b>	
<b>Approved By:</b>	<b>Malik Chibah</b>	<b>Signature:</b>	

<input type="checkbox"/> Mandatory <input checked="" type="checkbox"/> Strongly Recommended <input type="checkbox"/> Optional
---

## Subject: SPRINT V1.5.1. Software Release

As part of Sonardyne’s continuous programme of product development, we are pleased to announce the release of SPRINT V 1.5.1.440.

### Main features of this release:

- Support Syrinx Beam Level Aiding.
- Support SPRINT-Nav Internal Pressure Sensor.
- Support windows 7 and 10 only.
- Support UDP topside connection.
- Support LNavUTC message.
- Ability to provide SPRINT external time synch.
- Improved export/import of SPRINT complete configuration.

See SPRINT release notes for full list of changes.

\*Beam Level quoted performance in datasheet is for SPRINT-Nav and Sonardyne calibrated SPRINT with co-located Syrinx.

The following instrument firmware versions have been tested with this software version. As a minimum, these firmware versions must be installed in each component when used with this version of software.

Instrument	Firmware	Software	Version
Lodestar	3.02.00.1012	Fusion LBL	1.12.04 / 1.12.05
ROVNAV6 (6G) Type 8311	3.05.06.12	Janus	1.2.1.18
Syrinx	2.2.4.0		

If you are not the correct recipient for this information or you would like us to send this information to another person please respond to this email.

You will not automatically receive a copy of this software/firmware.

Should you require any further clarification please contact customer support on [support@sonardyne.com](mailto:support@sonardyne.com) or +44 1252 872288.