



# New Software/Firmware Release Notification

---

<b>Bulletin No.</b>	SF16-011	<b>Issue Date:</b>	1 <sup>st</sup> November 2016
<b>Issue/Revision:</b>	2	<b>No. of Pages:</b>	1
<b>Prepared By:</b>	R. Wilson (Snr.Customer Support Eng.)	<b>Signature:</b>	
<b>Approved By:</b>	E. Ceurstemont (Team Leader Subsea Products)	<b>Signature:</b>	

---

- |   |
|---|
| <input type="checkbox"/> Mandatory<br><input type="checkbox"/> Strongly Recommended<br><input checked="" type="checkbox"/> Optional (required if using Marksman/Ranger 2/Mini Ranger 2 All Variants v4.05 or later) |
|---|

## Subject: HPT Firmware V3.08.02.03 Release

As part of Sonardyne's continuous programme of product development, Sonardyne is pleased to announce a new release of HPT firmware (V3.08.02.03). This will firmware will provide:

- New functionality to support new variants such as the HPT2000 and HPT3000
- Bug fix to the CKHW command to ensure it does not falsely report fail when no hardware error exists
- Firmware changes to support new hardware revisions

This firmware is required if using Marksman/Ranger 2/Mini Ranger 2 all variants release version V4.05 or later.

If you are not the correct recipient for this information or you would like us to send this information to another person please respond to this email.

You will not automatically receive a copy of this software/firmware.

Should you require any further clarification please contact customer support on [support@sonardyne.com](mailto:support@sonardyne.com) or +44 1252 872288.